

Construction progress on the of secretariat office buildings and chambers .

On Friday 19 October 2018, at 09.30 hrs., secretary to Commission on Procurement Audit of New Parliamentary Construction with Components visited the site to monitor construction progress on the Secretariat of the Senate building, Senate Chamber building and office building of the Secretariat of the House of Representatives. At present, the cumulative percentage of construction progress is 53.25 on 12 October 2018.

ความก้าวหน้าการก่อสร้างอาคารสำนักงานเลขาธิการและห้องประชุม

วันศุกร์ที่ ๑๙ ตุลาคม ๒๕๖๑ เวลา ๐๙.๓๐ น. ฝ่ายเลขานุการคณะกรรมการตรวจการจ้างโครงการก่อสร้างอาคารรัฐสภาแห่งใหม่ พร้อมอาคารประกอบ ลงพื้นที่ตรวจสอบความคืบหน้าโครงการก่อสร้างฯ ในส่วนของงานความก้าวหน้าอาคารสำนักงานเลขาธิการวุฒิสภา ห้องประชุมวุฒิสภา อาคารที่ทำการสำนักงานเลขาธิการสภาผู้แทนราษฎร โดยปัจจุบันการดำเนินงานโครงการก่อสร้างฯ มีความคืบหน้าผลงานสะสมรวมทั้งโครงการ ณ วันที่ ๑๒ ตุลาคม ๒๕๖๑ คิดเป็น ๕๓.๒๕ เปอร์เซ็นต์



สำนักงานเลขาธิการสภาผู้แทนราษฎร




บริษัท ชีโน-ไทย เอ็นจิเนียริง แอนด์ คอนสตรัคชั่น จำกัด (มหาชน)

ภาพถ่ายความก้าวหน้าในส่วนห้องประชุม สว. รอบที่รายงาน



ภาพถ่ายความก้าวหน้าในส่วนห้องประชุม สส. รอบที่รายงาน



Infographics of construction progress : the upper photo is the construction progress of the Senate Chamber and the lower photo is the House of Representatives Chamber.

Source: The Official Facebook Page on the New Parliament Construction Project.